

Trusted to ensure.

 \diamond \diamond \diamond

FIRE RESISTANT TIMBER DOORSETS

Certificate Number: UKTC 1002

Certificate only valid if verified on website: www.uktc-ensure.com

Issued by United Kingdom Testing & Certification Ltd

This is to certify that



Wood International Agency

Wood House, 16 King Edward Road, Brentwood, Essex, CM14 4HL

Tel: +44 (0) 1277 232991

Email: doors@woodia.co.uk

Who manufacture door blanks used for the fabrication the following fire rated timber-based doors & doorsets:

MARKSMAN®

Marksman 44 - Fire Door System for 30 Minutes Fire Resistance

Manufactured at

Producing Factory W3 - Details held on file

have satisfied the requirements of the UKTC-SR-001 Rev 5 Timber Doorsets scheme. This includes the testing of products to BS 476-22:1987, the inspection of their factory production control, continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve 30 minutes integrity and insulation are detailed on page 2 of this certificate.

This certificate consists of 2 pages. Publication of this certificate is permitted.

Ian Laithwaite

Certification Manager

Laitwaite

Initial Certification: 20/05/2025 Page 1 of 2

Expires: 20/05/2030

Issue Number: 001

SCAN QR CODE TO VERIFY THIS CERTIFICATE







Trusted to ensure.

 \diamond \diamond \diamond

Certificate Number: UKTC 1002

The production of fire-resistant timber doors and doorsets are manufactured in accordance with assessment / test reports referenced within the following table:

Fire Rating	Report Owner	Assessment / Test Report
FD30	Wood International Agency	WF546313

The scope of the certification is limited to the details and parameters contained within the listed reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/revision of the listed reports are maintained as part of their audited factory production control system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.

Initial Certification: 20/05/2025 Page 2 of 2

Expires: 20/05/2030

Issue Number: 001

